

NOTE 3: NOS. 11601-11604 - CAST IRON OWNERSHIP PLATE
PER WP DRG. 543-F-330

NO. 11605-11606, - STENCILLED AS FOLLOWS:
11611 BANKERS TRUST COMPANY,
OWNER.

NO. 11609, 11610 - STENCILLED AS FOLLOWS:
THE CHASE MANHATTAN
BANK, OWNER.


NO. 11607 - STENCILLED AS FOLLOWS:
BANK OF AMERICA
NATIONAL TRUST AND SAVINGS
ASSOCIATION, OWNER.

NO. 11608 - CAST IRON OWNERSHIP PLATE
PER WP DRG. 543-F-330

NOTE:
THE FOLLOWING DRAWINGS OF LETTERS AND
NUMERALS TO APPLY-

624-F-340 2" BLOCK LETTERS AND NUMERALS.
624-F-300 3" BLOCK LETTERS AND NUMERALS
623-F-310 4" BLOCK NUMERALS.
624-F-350 4" BLOCK LETTERS.
624-F-360 7" BLOCK NUMERALS
624-F-330 9" BLOCK LETTERS "P TO W"
623-F-300 LUBRICATION DATE STENCILING.

OWNERSHIP STENCILING,
IN 1" HIGH LETTERS, 1" SPACES,
OR OWNERSHIP PLATE
AS REQUIRED. SEE NOTE 3.



LOCATE ON BOLSTER
WEB PLATE


NOTE: DEFECT CARD
RECEPTACLE LOCATED
PER AAR RULE NO. 49

MILLER LUBRICATORS

REPACK OR LUBRICATION DATE
PER DWG. 623-F-300
SEE TABLE "B"

WITH OR NONE
SEE TABLE "A"

SHARP OBJECTS MUST NOT
CONTACT LINING OF AIRSLIDE
DO NOT STEAM INTERIOR
OR CLEAN WITH WATER.



NOTE 1: ALL LETTERING AND MARKINGS TO BE BLACK UNLESS
OTHERWISE SPECIFIED.

NOTE 2: ALL LETTERS AND FIGURES 3" OR OVER IN HEIGHT ARE TO BE
SOLID AND NOT DISCONNECTED AT BRIDGES.

LUBRICAT	NONE	AIRSLIDE COVERED HOPPER 11609-11611	F-1202	GAFC DWG. 4-6312-C
LUBRICAT	NONE	AIRSLIDE COVERED HOPPER 11605-11608	F-1201	GAFC DWG. 4-6312-B
REPACK	WITH	AIRSLIDE COVERED HOPPER 11601-11604	F-1200	GAFC DWG. 4-6312-A
B	A	WHERE USED	CARD	REF.
4053	F			
10-4-61	F			
2039	E			
2030	E			
11-28-60	D			
3994	C			
3991	B			
3990	B			
1-22-53	A	DR. JUEL CH. ADOR AP. 11811		
REVISED		DATE: JULIE 11, 1958		
WESTERN PACIFIC RAILROAD CO. MECHANICAL DEPT. PAINTING & STENCILING ARRANGEMENT				
624-F-1200				

253

This file (624-F-1200_Painting_and_Stenciling_Airslide_CVR_Hoppers.pdf) was posted to
WPLives.org at Sat Aug 1 02:20:20 PM PDT 2026