

October 2016 Caboose seat progress:

01414 Rio Grande Cupola

Four 20X36 seat backs with plywood .
Complete

13878 Mo Pac

Three 20X20 seat bottoms used wood.
Six arm rests 2x12 with new plywood.
Complete

UP 24592 Rock Island

One 62X24 seat cushion with plywood bottom.
One 55x24 seat cushion with plywood bottom.
Complete

SP 25283 Cupola

Three 37X24 seat cushion with plywood bottom.
Three 34X24 seat cushion with plywood bottom.
Two 63X24 seat cushion with plywood bottom.
Complete

SP 25732 Cupola

Three 21X21 seat's with new plywood bottom.
One 21X18 seat bottom with plywood bottom.
Six 2X8 arm rests with plywood bottom.
Complete

SP4706 Christine.

Replacement of various seats and backs are on hold for now.
Picture of 11 Of the 15 seat bottoms redone.

